

**Work Order ID 116156**

Monday, April 07, 2014 1:39:44 PM

**\*116156\***

Page 1

Item ID: D2844-1

Accept

**\*N900040100\***

Setup Start

**\*NS1\***

Revision ID:

Stop

**\*NS2\***

Item Name: Arms

Start Date: 4/7/2014 Start Qty: 4.00

**\*4\***

Cust Item ID:

Required Date: 4/8/2014 Req'd Qty: 4.00

**\*4\***

Customer: CRLCL01

Reference: RMA RA111725

Approvals: Process Plan: ME Date: 14-4-7  
QC: \_\_\_\_\_ Date: \_\_\_\_\_Tooling: \_\_\_\_\_ Date: \_\_\_\_\_  
SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Run Start

**\*NR1\***

Stop

**\*NR2\***Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool # Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

Draw Nbr

Revision Nbr

D2844

Rev A

100

**\*100\***

QC

Quality Control

Memo

INSPECT RA 111725  
D2844-1 X 2 B89332, 2 X 61155

RE-INSPECT AND ID UNDER NEW BATCH NUMBER

0.00

DAS  
27  
9-89

0.00

14/4/14

4

110

**\*110\***

Packaging

Packaging

Identify as per dwg &amp; Stock Location: \_\_\_\_\_

0.00

Memo

2X PPP 116189  
2X PPP 112935

0.00

DAS  
28  
9-89

4X

APR 14 2014

120

**\*120\***

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

MLJ 14-04-15

MLJ 14-04-15

# Picklist Print

Monday, April 07, 2014 1:39:41 PM

Page 1

Work Order ID: 116156

**\*116156\***

Parent Item: D2844-1

**\*D2844-1\***

Parent Item Name: Arms

Start Date: 4/7/2014

Required Date: 4/8/2014

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP: B00.11.01Removed P/O for Powder Coat - in house processEC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2844-1		Manufactured	No				Each	10.0000		4			
<b>*D2844-1*</b>									<b>**</b>				
Arms													

Location

Loc Qty

Loc Code

ST258

10

109149

8

89332

2

2 x 84382  
2 x 61135  
MIS  
14-4-7

**RA111725 D2844-1 B89332/B61155**  
**D2844-3 B50825/B74695**

RECEIVED APRIL 4, 2014  
INSPECTED APRIL 4, 2014

CUSTOMER: RLC LLC  
CONTACT: JOHN GILLEY  
SHIPPED FROM: BROUSSARD, LA, US

**Instructions for RA111725 D2844-1 B89332/B61155**  
**D2844-3 B50825/B74695**

- Fully inspect part
- Re-identify with new tag
- Return to stock under new w/o

**Time Estimate** = 2 HOURS

**Departments Required:** stores

**Pictures Attached** = N/A

**QTY INSPECTED** = X2 D2844-1 B89332  
X2 D2844-1 B61155  
X1 D2844-3 B50825  
X1 D2844-3 B74695

**THIS INSTRUCTION SHEET MUST  
BE ATTACHED TO THE  
RESTOCKING WORK ORDER AT  
ALL TIMES!!!!**